

Release Notes for...

Tocoman iLink 4.0.3

New Features

- Supports Windows 64bit operating systems
- Faster communication with Tocoman Express Server
- New tooltips added to the user interface
- Support for curtain walls
- Improved calculation method for zone's various floor areas

Known Issues

- Model Browser's Overview tab is not updated automatically, if you e.g. create a new group. You need to close the window and re-open before different fields are updated.
- The order of grouping criteria in Model Browser's Advanced Wizard is not stored. This might affect the results, if you use the settings with various model versions.
- Sorting quantity columns uses a string based comparison instead of number. If you have e.g. values "1 m2", "2 m2" and "101 m2", the resulting order will be "1 m2", "101 m2" and "2 m2".
- Default settings of the Graphisoft ArchiCAD contain single character shortcut keys (e.g. "a" and "s"). These shortcut keys cause unexpected behaviour in certain use cases. Entering character "a", for example, into the Model Browser's search field can launch an ArchiCAD command.