

## Release Notes for...

# Tocoman iLink 4.1

## New Features

- Added 2 new objects (see list below)
  - Shell
  - Skylight
- Added “Renovation, status” property to all objects
- Added following properties to “Wall” object
  - Area, side, conditional, larger
  - Area, side, conditional, smaller
  - Area, side, conditional, average
  - Area, side, conditional, left
  - Area, side, conditional, right
  - Area, side, conditional, reference side
  - Area, side, conditional, opposite of reference side
  - Area, side, gross, reference side
  - Area, side, gross, opposite of reference side
  - Area, sides, conditional
- Added following properties to “Window” object
  - Length, frame
- Added following properties to “Slab” and “Roof” objects
  - Area, conditional

## Bug Fixes

- Problems with ArchiCAD 14 crashing during a visualization operation in iLink seem to be solved. If you notice similar problems in ArchiCAD 15 version, please contact our [support](#).

## Known Issues

- Model Browser’s Overview tab is not updated automatically, if you e.g. create a new group. You need to close the window and re-open before different fields are updated.
- Sorting quantity columns uses a string based comparison instead of number. If you have e.g. values “1 m2”, “2 m2” and “101 m2”, the resulting order will be “1 m2”, “101 m2” and “2 m2”.
- “Link with Cost Estimating” dialog does not display recipe’s unit before it has links. The unit will be visible e.g. when creating the link in “Linking Properties” dialog.